



## True North Pendant

### Supplies:

Feather pendant  
32 x 14mm Art Metal blank  
30mm brass ring  
15mm Art Metal jump ring  
7mm gunmetal jump ring  
1 6mm glass bead  
3" waxed linen  
2" 19 gauge steel wire  
18" gunmetal chain

**Tools:** Bench block, letter stamps, hammer, round and chain nose pliers, wire cutters, buffing block or steel wool.

### Directions:

1. Stamp True North unto the arte metal blank. Buff with buffing block or steel wool to lighten the metal, leave the letters dark. Add to the large brass ring with the jump ring.
2. With the round nose pliers create a large loop with the steel wire 1" from the bottom. With the chain nose pliers open the loop and add the feather pendant, close the loop. Wrap the tail of the 1" wire around the top of the feather.
3. With the round nose pliers create a loop at the top of the feather, open the loop with the chain nose pliers and slide the brass ring in the loop, close the loop. Wire wrap the wire several times under the loop creating a messy wrap, trim the wire and use the chain nose pliers to tuck in the end of the wire.
4. Wrap the linen around the brass ring twice, with both ends tie a knot, string on the glass bead, tie both ends into a knot at the bottom of the bead. Tie a knot on each thread at the bottom, leaving a 1/4" of linen.
5. Add the 15mm jump ring to the top of the brass ring, add on the chain.